

Handles / Brass



Handles / Brass

Treatment with three processing steps:



1. step: **Smoothing**

Abrasive media: **PH-4-Z**

Compound: **paste 9056**

Machine: **VA 140** **treatment time : 8 hours.**



Handles / Brass

Treatment

with three processing steps:



2. step: **Rinsing**

Abrasive media: **PH-4-Z**

Compound: **water**

Machine: **VA 140** Treatment time: **15 min.**



Handles / Brass

Treatment

with three processing steps:



3. Step: **polishing**

Abrasive media: **PH-4-Z**

Compound: **D-670-U**

Machine: **VA 140** Treatment time: **45 min.**

